

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #1

Date: 11/20/2015

Comments: Background sample collected from College Park located approximately half a mile southeast of the facility.

COC No. 52390-01



Photograph #2

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-02

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #3

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-03



Photograph #4

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-04

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #5

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-05



Photograph #6

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-06

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #7

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-07



Photograph #8

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-08 & -09 (Dup)

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #9

Date: 11/20/2015

Comments: Soil Sample

COC No. 52390-10



Photograph #10

Date: 11/20/2015

Comments: Soil Sample

COC No. 52391-01

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis




Photograph #11

Date: 11/20/2015

Comments: Soil Sample

COC No. 52391-02 & -03 (Dup)



Photograph #12

Date: 11/20/2015

Comments: Soil Sample

COC No. 52391-04

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #13

Date: 11/20/2015

Comments: A piece of grinding grit located at the southeast corner of the fence.



Photograph #14

Date: 11/20/2015

Comments: Grinding grit fragments observed in this area near the southeast property line within some trees and brush.

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #15

Date: 11/20/2015

Comments: A piece of grinding grit observed near the southeast property line near the fence.

COC No. 52391-05



Photograph #16

Date: 11/20/2015

Comments: Soil Sample

COC No. 52391-06

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #17

Date: 11/20/2015

Comments: Large mound of soil and wood. Grinding grit was observed in this area.



Photograph #18

Date: 11/20/2015

Comments: Large mound of soil and wood. Grinding grit was observed in this area.

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #19

Date: 11/20/2015

Comments: Grinding grit.



Photograph #20

Date: 11/20/2015

Comments: Soil Sample

COC No. 52391-07

Plating equipment and horses located on the other side of the fence. The adjacent property is also owned by Stag Management, the former operators of Lane Plating.

PHOTOGRAPHIC DOCUMENTATION

Investigation Date: 11/20/2015

Facility Name: Lane Plating

County: Dallas

EPA ID No: TXD007336571; SWR No: 31215

Investigator: Dorothy Lewis



Photograph #21

Date: 11/20/2015

Comments: Soil sample collected from a discolored area near the treatment building. A greenish substance appears to have been discharged from a tote next to the building.

COC No. 52391-08



Photograph #22

Date: 11/20/2015

Comments: Close-up of green discharge that discolored the rocks..